

CARR - 768

913 ARNOLD ROAD

late 19th century

Westminster vicinity

private

913 Arnold Road is a representative late nineteenth century farm complex. The farmhouse retains the regional style characteristics and is built into a slope. It has Victorian-style ornamentation in its porch and gabled dormer. There is a late nineteenth century bank barn with a board fence around the barnyard.



DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER:

CARR-768

NEGATIVE FILE NUMBER:

UTM REFERENCES:

Zone/Easting/Northing

U.S.G.S. QUAD. MAP:

Westminster

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: residence

ORIGINAL USE: residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent () Good (X)

Fair () Poor ()

THEME:

STYLE:

DATE BUILT:

late 19th century

COUNTY: CARROLL

TOWN: Westminster vicinity

LOCATION: 913 Arnold Rd.

TAX MAP 52 Block 10 P-55

COMMON NAME:

FUNCTIONAL TYPE: residence

OWNER: Rodney E. Hirt

ADDRESS: 913 Arnold Rd. Westminster

ACCESSIBILITY TO PUBLIC:

Yes () No (X) Restricted ()

LEVEL OF SIGNIFICANCE:

Local () State () National ()

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone (X) Brick () Concrete () Concrete Block ()
2. Wall Structure
 - A. Wood: Log () Post and Beam (X) Balloon ()
 - B. Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block ()
 - C. Iron () D. Steel () E. Other
3. Wall Covering: Weatherboard () German Siding () Board and Batten ()
Wood Shingle () Shiplap () Novelty () Stucco () Sheet Metal ()
Aluminum () Asphalt Shingle () Brick Veneer () Stone Veneer ()
Bonding Pattern: Other: *Asbestos Siding*
4. Roof Structure
 - A. Truss: Wood (X) Iron () Steel () Concrete ()
 - B. Other:
5. Roof Covering: Slate () Wood Shingle () Asphalt Shingle () Sheet Metal (X)
Built Up () Rolled () Tile () Other:
6. Engineering Structure:
7. Other:

Appendages: Porches (X) Towers () Cupolas () Dormers () Chimneys () Sheds ()
Ells (X) Wings () Other:Roof Style: Gable (X) Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
Saw Tooth () With Monitor () With Bellcast () With Parapet ()
With False Front () Other:

Number of Stories: 2 1/2

Number of Bays: 3 x 2

Approximate Dimensions:

Entrance Location: center

THREAT TO STRUCTURE:

No Threat () Zoning () Roads ()
Development () Deterioration ()
Alteration () Other:

LOCAL ATTITUDES:

Positive () Negative ()
Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

representative regional style
 gabled dormer
 built-in slope
 full-length porch

RELATED STRUCTURES: (Describe)

bank barn - late 19th century

STATEMENT OF SIGNIFICANCE:

representative late 19th century farmhouse and farmstead

REFERENCES:

1862 Martenet's Map:
 1877 LG & S Atlas: D. Zincken

SURROUNDING ENVIRONMENT:

Open Lane () Woodland () Scattered Buildings (X)
 Moderately Built Up () Densely-Built Up ()
 Residential () Commercial ()
 Agricultural () Industrial ()
 Roadside Strip Development ()
 Other:


RECORDED BY:

Joe Getty

ORGANIZATION:

DATE RECORDED:

8/83



U.S.G.S. MAP
WESTMINSTER, MD.
1:24000 SCALE

Mapped by the Corps of Engineers, U. S. Army
Edited and published by the Geological Survey



CARR-768

913 ARNOLD ROAD

Westminster vicinity

west facade

8/83

Photo By Joe Getty